## Oil Field Environmental Incident Summary

**Responsible Party:** WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: JONES 11-8H

Field Name: SANISH Well File #: 18085

Date Incident: 2/5/2016 Time Incident: 08:00 Facility ID Number:

County: MOUNTRAIL Twp: 154 Rng: 91 Sec: 8 Qtr: NW NW

Location Description:

Submitted By: Patrick McNamara Received By:

Contact Person: Patrick McNamara

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 4 Barrels 5 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/12/2016 Clean Up Concluded: 2/11/2016

Risk Evaluation:

None.

Areal Extent:

## Potential Environmental Impacts:

None.

## Action Taken or Planned:

Replace needle valve and inspect for signs of corrosion on a regular basis. Remainder of impacted soil with be scraped up and disposed of at an approved location.

Wastes Disposal Location: At an approved facility.

Agencies Involved:

## **Updates**

Date: 2/5/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, the release was contained. NDIC has oversight.